Division of Health Service Regulation (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES COMPLETED AND PLAN OF CORRECTION DENTIFICATION NUMBER: A. BUILDING: 01 B. WING 02/03/2016 HAL080026 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 612 HIGHWAY 152 EAST THE MEADOWS OF ROCKWELL RETIREMENT ROCKWELL, NC 28138 PROVIDER'S PLAN OF CORRECTION (X5) SUMMARY STATEMENT OF DEFICIENCIES ID (X4) ID (EACH CORRECTIVE ACTION SHOULD BE COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) C 000 C 000 Initial Comments This report is of a Biennial Construction Survey done by Bob Getchell and Dennis Harrell on February 3, 2016. This facility was first licensed as a Home for the Aged serving 120 residents on August 9, 1988. Therefore, this facility must meet the 1987 and the applicable portions of the 2005 Rules for the Licensing of Adult Care Homes, and, the 1978 North Carolina State Building Code (Revision 9) Section 409, Institutional Occupancy, Unrestrained. Deficiencies were noted which will require a new plan of correction. C 164 C 164 Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND **FURNISHINGS** (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: Based on observation, the resident furnishings in bedrooms were not maintained in clean condition. Findings include: Carpet has been a) An odor of urine was detected at the left end 03/08/16 of the 100 Hall corridor. Further inspection Cleaned revealed that Room 118 has badly stained carpet and is the source of the odors in the corridor.

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

anetto Koglis E

TITLE

3 18/16

If continuation she

STATE FORM

Division of Health Service Regulation (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: A. BUILDING: 01 AND PLAN OF CORRECTION 02/03/2016 B. WING HAL080026 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 612 HIGHWAY 152 EAST THE MEADOWS OF ROCKWELL RETIREMENT ROCKWELL, NC 28138 PROVIDER'S PLAN OF CORRECTION (X5)in SUMMARY STATEMENT OF DEFICIENCIES COMPLETE (EACH CORRECTIVE ACTION SHOULD BE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) TAG Toilet paper dispenser 03/01/16 C 164 C 164 Continued From page 1 b) The toilet paper dispenser is missing in the resident bathroom on the main hall C 166 C 166 Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards: (e) This Rule shall apply to new and existing facilities. beverage crate and stored safely into approved This Rule is not met as evidenced by: Based on observation, the building was not maintained free of hazards by improper storage of oxygen cylinders. This would affect all residents by potentially exposing them to hazards from a ruptured cylinder. Findings include: The oxygen bottles in Room 16 are being stored loose in a box, and also in beverage crates that can not prevent them from tipping over. C 189 Building Equipment Maintained Safe, Operating C 189 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.

Division of Health Service Regulation STATE FORM

5VQP21

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING HAL080026 02/03/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 612 HIGHWAY 152 EAST THE MEADOWS OF ROCKWELL RETIREMENT ROCKWELL, NC 28138 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLETE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG DEFICIENCY) C 189 | Continued From page 2 C 189 Century Link completed nucled repairs on 3/18/16 3/18/16 This Rule is not met as evidenced by: Based on observation, the building fire protection equipment was not maintained to keep the facility safe. This would affect all residents if the systems failed to suppress a fire. Findings include: a. Water could be heard running through the "dry" sprinkler pipe in the attic. Further investigation revealed that water was draining into a bucket inside the sprinkler riser room. Have the system checked and eliminate any intrusion of water into the dry pipe system in the attic. Based on observation, the building exit Kepaired 3/1/16 signage and emergency illumination were not maintained in a safe manner. This would affect all residents by not keeping the exits visible in an emergency. Findings include: Exit signs and emergency lights are not working Replaced batteries in emergency lights Buibs replaced in exit signs in the following locations: a) Emergency Light at B Hall Med Storage b) Emergency Light at Activity Room c) Exit sign at Dining Room exit to corridor d) Corridor Exit Sign near room 337 3. Based on observation, the building was not maintained in a safe manner by not maintaining the fire-resistance rating of building components. This would affect all residents by not containing smoke and fire in the room or smoke compartment of origin.

Findings include:

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: 01 B. WING 02/03/2016 HAL080026 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 612 HIGHWAY 152 EAST THE MEADOWS OF ROCKWELL RETIREMENT ROCKWELL, NC 28138 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 189 C 189 Continued From page 3 3/11/16 -All penetrations have a. The attic smoke barrier wall over room 311 has been repaired and tape has been fixed unprotected penetrations by a sprinkler pipe and other conduits, and the tape on the wall is coming 3/10/14 b. The attic fire wall over room 336 has - Repaired unprotected penetrations by a sprinkler pipe and other conduits. -Smoke barrier wall 3/10/14 c. The attic smoke barrier wall over room 124 has has had all penetrations unprotected penetrations by a sprinkler pipe and other conduits, repaired d. The attic smoke barrier wall over room 124 has a smoke damper which failed to close when Smoke damper being repaired by Chris Register 3/18/16 the test switch was activated. e. In the Kitchen Dry Stores room there is an Kitchen Drystore Penetratia 02/23/16 in ceiling repaired unprotected ceiling penetration by conduit f. In the Kitchen Office a plastic access panel has been used to cover a hole in the wall to the kitchen. -Plastic panel has been replaced 3/10/14 with sheetrock g. In the corridors some of the modems installed near the ceiling have unprotected penetrations by wire above them. - Fire proof could has been put in to fill penetrations in There are unprotected ceiling penetrations in the Medical Records office. i. There are unprotected ceiling penetrations in ceiling near modern; medical office staff lowinge relectrica 3/1/16 the Staff Lounge. j. There are unprotected ceiling penetrations in the Electrical Room accross from the office. k. There are unprotected ceiling penetrations in the Shower Room on the 100 Hall. 100 hall These unprotected openings are not in conformance with the requirement to use a through penetration fire stop system that has been tested in accordance with ASTM E-814. Based on observation, the facility components were not maintained operable by having doors that did not close easily and latch.

Findings include:

Division of Health Service Regulation (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING: 01 B. WING 02/03/2016 HAL080026 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 612 HIGHWAY 152 EAST THE MEADOWS OF ROCKWELL RETIREMENT ROCKWELL, NC 28138 (X5) COMPLETE PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) A. Replaced hinge

B. Repaired Gate

C. Removed Stopper on
Kitchen door 2/23/16 C 189 C 189 Continued From page 4 a) Bedroom 331 door is being held open b) Exit gate between C Hall and Dining Room drags floor and is hard to open Both Kitchen doors to the Dining Room are wedged open d) Kitchen door to dry stores is blocked and can D. Moved shelf in dry Storage so door can close. not be closed